## Exhibit 26

From: Kimberly Healy [khealy@starbucks.com]

**Sent**: 1/19/2018 8:15:17 AM

To: Rami Kranz [rkranz@starbucks.com]; Jasmine Onumah [jonumah@starbucks.com]
CC: Stephen Gallant [sgallant@starbucks.com]; Margaret Kis [mkis@starbucks.com]


Subject: Hot Shot Sighting


## Sharing – Rockefeller Concourse

In addition to the 3-DR reach-in fridge missing its top cover, having excessive build-up and debris - 5 hot shots found. Also found another 2 in the base of their hot water heater (Jasmine- similar to 7465, 59<sup>th</sup> & Columbus with Carrie).

I will be seeing the DM later and coaching the new SM that transferred-in this week.









Confidential DEF0025583